
MATERIAL SAFETY DATA SHEET

HELENA LABORATORIES
1530 Lindbergh Dr./P.O. Box 752
Beaumont, TX 77704-0752
USA Toll Free 800-231-5663

DATE PREPARED: 4/18/2001
REVISION: 1

1. IDENTIFICATION:

PRODUCT NAME: REP ULTRA SPE-16 (PONCEAU S) KIT
PRODUCT NO.: 3155

=====

2. INGREDIENTS (THE ABOVE KIT CONTAINS THE FOLLOWING ITEMS):

Table with 3 columns: PRODUCT NUMBER, PRODUCT IDENTIFICATION (LABEL NAME), COMMENTS. Includes entries for PONCEAU S STAIN and REP ULTRA SPE-16 GEL.

=====

ATTACHED IS THE MSDS FOR THE ABOVE NAMED HAZARDOUS INGREDIENT.

4. HEALTH HAZARD DATA:

PRIMARY ROUTE(S) OF ENTRY:

INHALATION? YES SKIN? YES INGESTION? YES

CARCINOGENICITY: NTP? NO IARC? NO

ACUTE EFFECTS OF OVEREXPOSURE:

EYES: CAUSES EYE IRRITATION.

SKIN: MAY BE HARMFUL IF ABSORBED THROUGH THE SKIN. CAUSES SKIN IRRITATION.

INHALATION: MAY BE HARMFUL IF INHALED. MATERIAL IS IRRITATING TO UPPER RESPIRATORY TRACT.

INGESTION: MAY BE HARMFUL IF INGESTED. MATERIAL IS IRRITATING TO THE MUCOUS MEMBRANES.

CHRONIC EFFECTS OF EXPOSURE: TO THE BEST OF OUR KNOWLEDGE, THE CHEMICAL, PHYSICAL AND TOXICOLOGICAL PROPERTIES HAVE NOT BEEN THOROUGHLY INVESTIGATED.

TOXICITY DATA: NIF

MEDICAL CONDITIONS AGGRAVATED BY EXPOSURE: NIF

EMERGENCY AND FIRST AID PROCEDURES:

EYE CONTACT: IN CASE OF CONTACT, IMMEDIATELY FLUSH EYES WITH COPIOUS AMOUNTS OF WATER FOR AT LEAST 15 MINUTES. CALL A PHYSICIAN.

SKIN CONTACT: IN CASE OF CONTACT, IMMEDIATELY WASH SKIN WITH SOAP AND COPIOUS AMOUNTS OF WATER FOR AT LEAST 15 MINUTES. CALL A PHYSICIAN.

INHALATION: IF INHALED, REMOVE TO FRESH AIR. IF NOT BREATHING, GIVE ARTIFICIAL RESPIRATION. IF BREATHING IS DIFFICULT, GIVE OXYGEN. CALL A PHYSICIAN.

INGESTION IF SWALLOWED, WASH OUT MOUTH WITH WATER PROVIDED PERSON IS CONSCIOUS. CALL A PHYSICIAN.

=====

5. FIRE AND EXPLOSION HAZARD DATA:

FLASH POINT (METHOD USED): NA

FLAMMABLE LIMITS: LEL NA UEL NA

EXTINGUISHING MEDIA: WATER SPRAY. CARBON DIOXIDE, DRY CHEMICAL POWDER OR APPROPRIATE FOAM.

SPECIAL FIRE FIGHTING PROCEDURES: WEAR SELF-CONTAINED BREATHING APPARATUS AND PROTECTIVE CLOTHING TO PREVENT CONTACT WITH SKIN AND EYES.

UNUSUAL FIRE AND EXPLOSION HAZARDS: EMITS TOXIC FUMES UNDER FIRE CONDITIONS.

=====
6. REACTIVITY DATA:

STABILITY: UNSTABLE: STABLE: X

INCOMPATIBILITY (MATERIALS TO AVOID): STRONG OXIDIZING AGENTS.

HAZARDOUS DECOMPOSITION OR BY-PRODUCTS: TOXIC FUMES OF CARBON MONOXIDE, CARBON DIOXIDE, NITROGEN OXIDES AND SULFUR OXIDES.

HAZARDOUS POLYMERIZATION:
MAY OCCUR: WILL NOT OCCUR: X

=====
7. SPILL OR LEAK PROCEDURES:

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED: WEAR RESPIRATOR, CHEMICAL SAFETY GOGGLES, RUBBER BOOTS AND HEAVY RUBBER GLOVES. SWEEP UP, PLACE IN A BAG AND HOLD FOR WASTE DISPOSAL. AVOID RAISING DUST. VENTILATE AREA AND WASH SPILL SITE AFTER MATERIAL PICKUP IS COMPLETE.

WASTE DISPOSAL METHODS: OBSERVE ALL FEDERAL, STATE AND LOCAL REGULATIONS.

=====

8. SPECIAL PROTECTION INFORMATION:

RESPIRATORY PROTECTION (SPECIFY TYPE): NIOSH/MSHA-APPROVED

VENTILATION: LOCAL EXHAUST: MECHANICAL: X
OTHER:

PROTECTIVE GLOVES: COMPATIBLE CHEMICAL-RESISTANT

EYE PROTECTION: CHEMICAL SAFETY GOGGLES

OTHER PROTECTIVE EQUIPMENT: SAFETY SHOWER AND EYE BATH.

=====
9. SPECIAL PRECAUTIONS:

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORAGE: DO NOT BREATH DUST.
AVOID CONTACT WITH EYES, SKIN AND CLOTHING. WASH THOROUGHLY
AFTER HANDLING. KEEP TIGHTLY CLOSED. STORE IN A COOL DRY PLACE.

OTHER PRECAUTIONS:

=====
10. OTHER INFORMATION:

The information herein is given in good faith but no warranty,
expressed or implied, is made.